Operator: AMEREN ILLINOIS COMPANY	Operator ID#: 32513	
Inspection Date(s): 3/11/2014, 3/12/2014, 3/13/2014	Man Days: 3	
Inspection Unit: Pana	·	
Location of Audit: Pana		
Exit Meeting Contact: Kevin Glaspy		
Inspection Type: Standard Inspection - Record Audit		
Pipeline Safety Representative(s): Donald Hankins		
Company Representative to Receive Report: Michael Fuller		
Company Representative's Email Address: mfuller2@ameren.com		

Headquarters Address Information:	300 Liberty	
	Peoria, IL 61602	
	Emergency Phone#:	
	Fax#:	
Official or Mayor's Name:	Ron Pate	
	Phone#: (217) 424-6518	
	Email:	
Inspection Contact(s)	Title	Phone No.
Kevin Glaspy	Quality Assurance Specialist	
ViAnna Thomas	Supervisor Gas Operations	

Gas System Operations	Status
Gas Transporter	Panhandle
Annual Report (Form 7100.1-1) reviewed for the year:	Not Checked
General Comment:  These records were inspected in the Pawnee Training Center.	
Unaccounted for Gas	1 11 12 1 1
General Comment:	Not Checked
These records were inspected in the Pawnee Training Center.	
Number of Services	Not Checked

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

General Comment:		
These records were inspected in the Pawnee Training Center.		
Miles of Main		Not Checked
General Comment:		
These records were inspected in the Pawnee Training Center.		
s the operator maintaining documentation verifying	their Maximum Allowable Operating Pressure(s)? (MAOP)	Satisfactory
General Comment:		
This information is being kept on the regulator station inspection	n sheets.	
Operating Pressure (Feeder)		Various
Operating Pressure (Town)		Various
Operating Pressure (Other)		Various
MAOP (Feeder)		Various
MAOP (Town)		Various
MAOP (Other)		Various
Does the operator have any transmission pipelines?		Yes
General Comment:		
Transmission records were inspected in the Decatur Plaza by C	Charles Gribbins.	
Regulatory	Reporting Records	Status
[191.5]	Were Telephonic Notices of Incidents reported to the NRC (800-424-8802)?	Not Checked
General Comment:		
These records were inspected in the Pawnee Training Center.		
[191.9(a)]	Was a DOT Incident Report Form F7100.1 submitted within 30 days after detection of an incident?	Not Checked
General Comment:		
These records were inspected in the Pawnee Training Center.		
[191.9(b)]	Were any supplemental incident reports submitted when deemed necessary?	Not Checked
General Comment:		
These records were inspected in the Pawnee Training Center.		
Did the operator have any plastic pipe failures in th	e past calendar year?	No
General Comment:		

AMEREN ILLINOIS COMPANY/3-13-2014

Page 2 of 13

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

No plastic pipe failures in the last calendar year in the Par	na Operating Center.	
Did the operator take action to mitigate safety components?	concerns relating to the failure of the PE or pipeline	Not Checked
General Comment:		
These records were inspected in the Pawnee Training Ce.	nter.	
[191.23(a)]	Did the operator report Safety Related Conditions?	Not Checked
General Comment:		
These records were inspected in the Pawnee Training Ce.	nter.	
[191.25]	Did the Operator file a Safety Related Condition Report within 5 working days of determination, but not later than 10 working days after discovery?	Not Checked
General Comment:		
These records were inspected in the Pawnee Training Ce.	nter.	
[192.16(c)]	Customer Notification: Has the operator notified each new customer within 90 days about the customer's responsibility regarding buried piping, however, operators of a master meter may continuously post a general notice in a permanent location?	Not Checked
General Comment:		
These records were inspected in the Pawnee Training Ce.	nter.	
C	RUG TESTING	Status
Category Comment:		
Drug records were inspected in 2011 at the St. Louis gene	eral office building headquarters.	
Refer to Drug and Alcohol Inspection Forms a	nd Protocols	Not Checked
TES <sup>-</sup>	TEST REQUIREMENTS	
[192.517(a)][192.505,192.507,192.511(c)]	Are pressure test records being maintained for piping operating above 100 psig?	Satisfactory
[192.517(b)][192.511,192.509,192.513]	Are pressure test records being maintained for at least 5 years on piping operating below 100 psig?	Satisfactory
[192.603(b)][192.725]	Were service lines temporarily disconnected from the main properly tested prior to reconnection?	Satisfactory
UPRATING		Status
[192.555][192.555]	Has the operator maintained documentation of uprating activities when uprating a pipe to a pressure that will produce a hoop stress of 30% or more SMYS?	Not Applicable
General Comment:		

AMEREN ILLINOIS COMPANY/3-13-2014

Page 3 of 13

No uprating to produce a hoop stress above 309	% smys, during the last year.	
[192.557][192.557]	Has the operator maintained documentation of uprating activities when uprating a pipe to a pressure that will produce a hoop stress of less than 30% SMYS?	Satisfactory
	OPERATIONS	Status
[192.603(b)][192.605(a)]	Has the operator conducted a review of the Operations and Maintenance Manual once per yr/15 months?	Not Checked
General Comment:		
These records were inspected in the Pawnee Tr	raining Center.	
Has the operator conducted a review of	of the Operator Qualification Plan once per yr/15 months?	Not Checked
General Comment:		
These records were inspected in the Pawnee Tr	raining Center.	
[192.603(b)][192.605(b)(3)]	Are construction records, maps, and operating history available to operating personnel?	Satisfactory
General Comment:	·	
Construction records and maps are available to	all personnel performing covered tasks.	
[192.603(b)][192.605(b)(8)]	Has the operator periodically reviewed personnel's work to determine the effectiveness of normal O&M procedures when deficiencies are found?	Not Checked
General Comment:	<u>'</u>	
These records were inspected in the Pawnee Tr	raining Center.	
CONTIN	IUING SURVEILLANCE RECORDS	Status
[192.603(b)][192.613(a)]	Has the operator reviewed continuing surveillance records for class location changes, failures, leak history, corrosion, changes in cathodic protection, and other unusual operating and maintenance conditions?	Not Checked
General Comment:	·	
These records were inspected in the Pawnee Tr	raining Center.	
[192.491][192.489]	Does the operator have records verifying if exposed cast iron was examined for evidence of graphitization and if necessary what appropriate action was taken concerning graphitization?	Not Applicable
General Comment:	·	
These records were inspected in the Pawnee Tr	raining Center.	
[192.603(b)][192.755]	Does the operator have surveillance records of cast iron pipelines, including appropriate action resulting from	Not Applicable

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

	tracking circumferential cracking failures, study of leak history, or any other unusual operating and maintenance conditions?	
General Comment:		
Ameren has no cast iron in the system.		
[192.603(b)][192.753(a)]	Is each cast iron caulked bell and spigot joint that is subject to a pressure of more than 25 (psig.) sealed as required?	Not Applicable
General Comment:		
Ameren has no cast iron in the system.		
[192.603(b)][192.753(b)]	Is each cast iron caulked bell and spigot joint that is subject to a pressure of 25 (psig.) or less and is exposed for any reason sealed as required?	Not Applicable
General Comment:		
Ameren has no cast iron in the system.		
QUALIFICATION (	OF PIPELINE PERSONNEL	Status
Refer to operator Qualification Inspection Forms a	and Protocols	Not Checked
General Comment:		
These records were inspected in the Pawnee Training Center.		
DAMAGE PR	EVENTION RECORDS	Status
Category Comment:		
These records were inspected in the Pawnee Training Center.		
[192.603(b)][191.11(a)]	Did the operator track the number of damages per 1000 locate requests for the previous years?	Not Checked
Has the number of damages increased or decreas	sed from prior year?	Not Checked
[192.603(b)][192.617]	Does the operator track records of accidents due to excavation damage to ensure causes of failures are addressed to minimize the recurrence?	Not Checked
[192.603(b)][192.614(c)(3)]	Does the operator provide documentation pertaining to notification of excavation, marking, positive response, and the availability and use of the one call system?	Not Checked
Does the operator have a Quality Assurance Progfacilities?	ram in place for monitoring the locating and marking of	Not Checked
Do pipeline operators include performance measu	res in facility locating contracts?	Not Checked
[IL ADM. CO.265.100(b)(1)]	Was third party damage to mains involving a release of gas reported to ICC JULIE Enforcement? http://www.icc.illinois.gov/julie/	Not Checked

AMEREN ILLINOIS COMPANY/3-13-2014

Page 5 of 13

Has the Operator adopted applicable section of the Common Ground Alliance Best Practices?		Not Checked
If no, were Common Ground Alliance Best Practices discussed with Operator?		Not Checked
	EMERGENCY PLANS	Status
[192.603(b)][192.615(b)(1)]	Are supervisors, responsible for emergency action, furnished copies of the latest edition of the Emergency Plan?	Satisfactory
[192.603(b)][192.615(b)(2)]	Has the operator maintained documentation that the appropriate operating personnel have received training to assure they are knowledgeable of emergency procedures and that the training was effective?	Not Checked
General Comment:		
These records were inspected in the Pawnee Tra	ining Center.	
[192.603(b)][192.615(b)(3)]	Has the operator maintained documentation of employee activity reviews to determine whether the procedures were effectively followed in each emergency?	Not Checked
General Comment:	·	
These records were inspected in the Pawnee Tra	ining Center.	
[192.603(b)][192.615(c)]	Has the operator maintained documentation that the operator established and maintained liaison with appropriate fire, police and other public officials?	Not Checked
General Comment:		
These records were inspected in the Pawnee Tra	ining Center.	
[192.603(b)][192.615(a)(3)]	Did the review of emergency response time intervals regarding odor/leak complaint documentation indicate adequate emergency response intervals were achieved?	Not Checked
General Comment:		
These records were inspected in the Pawnee Tra-	ining Center.	
PUBLIC AWARENESS PROGRAM - RECORDS		Status
Refer to Public Awareness Program Inspection Forms and Protocols		Not Checked
General Comment:		
These records were inspected in the Pawnee Tra	ining Center.	
	ODORIZATION OF GAS	Status
[192.603(b)][192.625(f)]	Has the operator maintained documentation of odorant concentration level testing using an instrument?	Satisfactory
[192.603(b)][192.625(e)]	Has the operator maintained documentation of odorizer	Satisfactory

	tank levels?	
[192.603(b)][192.625(f)(1)]	Are master meter operators receiving written verification of odorant concentration levels from their gas supplier?	Not Checked
General Comment:		
Ameren Illinois is not a master meter operator.		
[192.603(b)][192.625(f)(2)]	Has the master meter operator maintained documentation of sniff tests performed as required by this section?	Not Checked
General Comment:		
Ameren Illinois is not a master meter operator.		
PATROLLIN	IG & LEAKAGE SURVEY	Status
[192.603(b)][192.721(b)(1)]	Is the operator patrolling business districts at a minimum of 4 per year/4 1/2 months?	Not Checked
General Comment:		
These records were inspected in the Pawnee Training Cer	nter by Charles Gribbins.	
[192.603(b)][192.721(b)(2)]	Is the operator patrolling outside business districts at a minimum of 2 per year/7 1/2 months?	Not Checked
General Comment:		
These records were inspected in the Pawnee Training Cer	nter by Charles Gribbins.	
[192.603(b)][192.723(b)(1)]	Is the operator performing leakage surveys in business districts at a minimum of 1 per year/ 15 months? If the operator has inside meter sets that meet this criterion then were those surveyed?	Satisfactory
[192.603(b)][192.723(b)(2)]	Is the operator performing leakage surveys outside a business district at a minimum of every 5 years/63 months? Is the operator performing leakage surveys on cathodically unprotected pipelines at a minimum of every 3 years/39 months? If the operator has inside meter sets that meet this criterion then were those surveyed? If the operator has yard lines then are those being surveyed?	Satisfactory
YARD L	INES - RESIDENTIAL	Status
[220 ILCS 2.2.03]	Has the operator designated and documented the location of all services where the meter is located more than 3 feet away from the wall of a residence?	Satisfactory
[192.463,220 ILCS 2.2.03][220 ILCS 2.2.03]	Has the operator determined if cathodic protection is required on these services?	Not Applicable
General Comment:		
Ameren Illinois does not protect piping after the outlet side	of the meter set.	

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

[192.723(b)(1),192.723(b)(2)][220 ILCS 2.2.03]	After the determination of the cathodic protection requirements, has the operator surveyed each line within the required leakage survey intervals?	Satisfactory
ABANDONMENT or DEACTIVE	ATION of FACILITIES PROCEDURES	Status
[192.603(b)][192.727(b)]	Did the operator maintain documentation demonstrating that each pipeline abandoned in place was disconnected from all sources and supplies of gas, and purged of gas?	Satisfactory
[192.603(b)][192.727(c)]	Did the operator maintain documentation demonstrating that each inactive pipeline that is not being maintained under this part was disconnected from all sources and supplies of gas; purged of gas?	Satisfactory
[192.603(b)][192.727(d)]	Did the operator maintain documentation demonstrating that whenever service to a customer was discontinued access to gas was either; locked, prevented by a mechanical fitting, or disconnected from the gas supply and open pipe ends sealed?	Satisfactory
[192.603(b)][192.727(e)]	Did the operator maintain documentation when air was used for purging that a combustible mixture was not present after purging?	Satisfactory
[192.727(g)][192.727(g)]	Did the operator maintain documentation for each abandoned onshore pipeline facility that crosses over, under or through a commercially navigable waterway?	Not Applicable
General Comment:		

There are no commercially navigable waterways in Ameren Decatur territory.

PRESSURE LIMITING AND REGULATION		Status
[192.603(b)][192.739(a)]	Is the operator inspecting and testing the pressure limiting and regulating stations at a minimum of 1 per year/15 months?	Satisfactory
[192.603(b)][192.743(a)]	Is the operator inspecting pressure limiting and regulating stations for adequate capacity at a minimum of 1 per year/15 months?	Satisfactory
[192.603(b)][192.743(b)]	If the operator used calculations to determine sufficient capacity, were the calculation reviews documented at a minimum of 1 per year/15 months?	Satisfactory
[192.603(b)][192.741(a),192.741(b)]	Is each distribution system supplied by more than one district pressure regulating station, or where required by the operator on a system supplied by a single regulating station, equipped with telemetering or recording pressure gauges to indicate the gas pressure in the district?	Not Checked

These records are kept in Gas Control in the Springfield Office.

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

[192.603(b)][192.741(c)]	If there were indications of abnormally high- or low- pressure, were actions taken to correct any unsatisfactory operating conditions?	Not Checked
General Comment:		
These records are kept in Gas Control in the Springfield Office	ө.	
[192.603(b)][192.743(a),192.743(b),192.195(b)(2	Is overpressure protection provided by the supplier pipeline downstream of the take point?	Not Checked
General Comment:		
The supplier will not guarantee overpressure protection down	stream of the take-point.	
[192.603(b)][192.743(a)]	If Yes, does the operator have documentation to verify that these devices have adequate capacity?	Not Checked
General Comment:		
The supplier will not guarantee overpressure protection down	stream of the take-point. This would be handled by the transmission departme	ent.
VALVE	MAINTENANCE	Status
[192.603(b)][192.747(a),192.747(b)]	Did the operator inspect and maintain distribution valves necessary for the safe operation of the system at a minimum of 1 per year/15 months?	Satisfactory
[192.603(b)][192.749(a)]	Did the operator inspect and maintain vaults > 200 cubic feet at a minimum of 1 per year/15 months?	Not Applicable
General Comment:		
Ameren Illinois in Pana has no vaults > 200 cubic feet in the s	system.	
Investiç	ation Of Failures	Status
[192.603(b)][192.617]	Did the operator experience accidents or failures requiring analysis?	Not Checked
General Comment:		
These records were inspected in the Pawnee Training Center	:	
WELDIN	G OF STEEL PIPE	Status
Category Comment:		
These records were inspected in the Pawnee Training Center	:	
[192.603(b)][192.225(b)]	Does the operator have documentation for their qualified welding procedure?	Not Checked
[192.603(b)][192.227,192.229]	Does the operator have documentation of welder qualification documentation as required?	Not Checked
[192.709][192.243(b)(2)]	Does the operator have documentation of NDT personnel qualification as required?	Not Checked

AMEREN ILLINOIS COMPANY/3-13-2014

Page 9 of 13

[192.709][192.243(f)]	Does the operator have documentation of NDT testing performed?	Not Checked
JOINING OF MATERIAL OTHER THAN WELDING		Status
Category Comment:		
These records were inspected in the Pawnee Training Center	er.	
[192.603(b)][192.285]	Are persons making joints with plastic pipe qualified?	Not Checked
[192.603(b)][192.287]	Are persons inspecting plastic pipe joints qualified?	Not Checked
[192.603(b)][192.283]	Are qualified joining procedures for plastic pipe in place?	Not Checked
CORROSIO	CONTROL RECORDS	Status
[192.491(a)][192.491(a)]	Has the operator maintained maps or records of cathodically protected piping, cathodic protection facilities, galvanic anodes, and neighboring structures bonded to the cathodic protection system?	Satisfactory
[192.491][192.459]	Has the operator maintained documentation of an examination when buried pipe was exposed?	Satisfactory
[192.491][192.465(a)]	Has the operator maintained documentation of annual pipe-to-soil monitoring performed at a minimum of 1 per yr/15 months and/or isolated services or short sections of main less than 100 feet at a minimum of 10% annually?	Satisfactory
[192.491][192.465(b)]	Has the operator maintained documentation of rectifier or other impressed current power sources inspections at a minimum of 6 per year/ 2 1/2 months?	Satisfactory
[192.491][192.465(c)]	Has the operator maintained documentation of each critical interference bond, reverse current switch, diode, etc. inspections at a minimum of 6 per year/ 2 1/2 months and/or non-critical interference bond inspections at a minimum of 1 per year/15 months?	Not Applicable
General Comment:		
No critical interference bonds in the system.		
[192.491][192.465(d)]	Has the operator taken prompt remedial actions to correct any deficiencies indicated by the monitoring?	Satisfactory
[192.491][192.465(e)]	Has the operator maintained documentation of unprotected pipeline surveys, inspections, or tests at a minimum of 3 years/39 months?	Not Applicable
General Comment:		
Pana has no unprotected gas lines in the system.		
[192.491][192.467(a),192.467(c),192.467(d)]	Has the operator maintained documentation of inspections or tests for electrical isolation at casings?	Satisfactory

[192.491][192.469]	Does the operator have a sufficient number of test stations or other contact points for electrical measurement to determine the adequacy of cathodic protection?	Satisfactory
[192.491][192.471]	Has the operator maintained documentation of corrective actions taken when a test lead is no longer electrically conductive?	Not Applicable
General Comment:	·	
All test leads are electrically conductive.		
[192.491][192.473(b)]	Has the operator maintained documentation of inspections or tests to assure their cathodic protection system is not affecting adjacent underground metallic structures?	Satisfactory
[192.491][192.475(a)]	Has the operator maintained documentation of investigations or steps taken to minimize internal corrosion due to transportation of corrosive gas?	Not Applicable
General Comment:	·	
Ameren has no corrosive gas in there system as far as they	know.	
[192.491][192.475(b)]	Has the operator maintained documentation of internal surface inspections performed when pipe is removed for any reason?	Not Applicable
General Comment:		
No pipe was removed the last two years.		
[192.491][192.477]	Has the operator maintained documentation of internal corrosion coupon monitoring at a minimum of 2 per year/ 7 1/2 months?	Not Checked
General Comment:		
These records were inspected at the Decatur Plaza by Cha	rles Gribbins.	
[192.491][192.481]	Has the operator maintained documentation of atmospheric corrosion control monitoring at a minimum of 1 per 3 years/ 39 months?	Satisfactory
[192.491][192.479]	Has the operator maintained documentation of corrective action where atmospheric corrosion was discovered?	Satisfactory
[192.491][192.483(a),192.483(b),192.483(c)]	Has the operator maintained documentation demonstrating that pipe removed due to external corrosion has been repaired or replaced with pipe that was coated and cathodically protected?	Not Applicable
General Comment:		
No pipe was removed.		
TRAINING	- 83 IL ADM. CODE 520	Status

Category Comment:				
All training records were inspected in the Pawnee operations center.				
[520.10(a) (1)]	Has the operator maintained documentation demonstrating that personnel have received adequate training?	Not Checked		
[520.10(a) (2)]	Do training records include verbal instruction and/or on the job training for each job classification?	Not Checked		
[520.10(b)]	Has the municipal operator maintained documentation demonstrating that personnel have received adequate training?	Not Applicable		
General Comment:				
Ameren Illinois is not a municipal operator.				
[520.10(a)(5)]	Are procedures periodically updated to include new materials, new methods of operation and installation, and changes in general procedures?	Not Checked		
General Comment:				
All training records were inspected in the Pawnee operations center.				